

Tetley's Motor Services Ltd

General - Migrated Risk Assessment for

Passenger Collection

Risks associated with passenger collection and drop off.

Reference number	Tet1872070	
Assessor	Michael Crooke	
Date completed	24/09/25	
Review Schedule	Annually	
Review date	24/09/26	
Approved date	24/09/25	
Approved by	Michael Crooke	
Affected site(s)	Tetleys Motor Services Ltd (LS10 1NY)	

Passenger Collection Page 2 of 6

Who is at risk?	
Driver, general public, passengers	
How is the risk controlled?	

A written risk assessment is attached in the client documents area.

Passenger Collection Page 3 of 6

Hazard









Moving Vehicles Passengers/Service Users In Vehic**l**es



People Movement (Risk of Slips)



Vehicle Movement



Work On or Near Live Roadways

Vehic**l**e

Passenger

Limits

Controls



Driving Risk Assessment -Vehicle Considerations



Seat Belts Fitted & Worn On Coach Journeys



Adequate Supervision Provided



First Aid Kit Carried In The Vehicle



All vehicles carry fire extinguishers



The calculated risk factor for this task / operation is **10.** (Probability: 2 X Severity: 5) This is classed as a Medium risk

Additional measures

None required

Safe operating procedures

Passengers to be picked up/dropped off with passenger door at kerb-side wherever possible. Passengers to remain seated and wear seat-belts. Passengers of school age and students to be adequatley supervised. Supervisors in charge of children should be aware of where emergency exits are. Driver not to move off whilst passengers are standing Any incidents to be reported to the office immediately

Assessor's signature: Michael Crooke Approved by signature: Michael Crooke

Passenger Collection

Page 5 of 6

Acknowledgements

The signs below acknowledge receipt of this risk assessment and confirm that they have read and understood the requirements of the risk assessment.

Full name	Signature	Date	Full name	Signature	Date

Review date: 24/09/26 Approved date: 24/09/25